

FLIP SEAT TAILGATE HARDWARE INSTALLATION

TSB161

PREPARED BY: Jonathan Kemp

DATE: 28 Oct 2013

Models affected: All flip seats

Description of action: To assure that all flip seat tailgates receive the correct hardware

Procedure: This requirement is very straightforward. There were a number of flip seats that were assembled using the incorrect hardware. Please inspect the assembly of the rubber retainers on your tailgate as pictured below. The fastener should be a 2-50616 #10 X 3/4" Pan Head Screw. That fastener may be incorrect, this is determined by measuring the length of the fastener. The incorrect fastener will measure 1" long, rather than the proper 3/4" fastener. If your fasteners measure 1" in length, please replace with appropriate hardware 3/4" in length. If these fasteners are not easily available locally, please call our customer service desk and request qty 4 of the 2-50616 fasteners. Please mention this Technical Service Bulletin and these fasteners will be shipped to you free of charge. In addition, these fasteners should be positioned as shown below, with the #10 nuts on the same side of the tailgate as the retainers. If these are facing the opposite direction, please remove and reverse them.

